

WASHINGTON TOWNSHIP PUBLIC SCHOOLS OFFICE OF THE SUPERINTENDENT 206 EAST HOLLY AVENUE SEWELL, NJ 08080

June 27, 2017

RE: Water Testing

Dear Washington Township Public School Community:

As you are aware, earlier this year we conducted the mandated testing of water for the presence of lead. Any outlet that tested in excess of 15.5 parts per billion (ppb) required remedial action. The US Department of Environmental Protection Agency (EPA) protocol for any outlet that exceeded the 15.5 ppb was to proceed with a flush sample. The flush sample has been completed, and the results are listed below. I am happy to report that only two (2) outlets retested require remedial action.

The first round of tests resulted in no results over the actionable amount of 15.5 ppb at Grenloch Terrace Early Childhood Center, Hurffville Elementary School and Thomas Jefferson Elementary School. However, the first round of tests did show the following outlets over the actionable amount requiring a second round of flush testing as follows:

	<u>Initial Test</u>	Initial <u>Remediation</u>	<u>Flush Test</u>	Remediation		
Bells Elementary School						
Bubbler F16	287	Disconnected	<15.5 ppb	N/A		
Bubbler R6	15.9	Disconnected	<15.5 ppb	N/A		
Birches Elementary Schoo	<u>l</u>					
Bubbler F3	71.4	Disconnected	<15.5 ppb	N/A		
Bubbler F14	21.2	Disconnected	<15.5 ppb	N/A		
Bubbler F18	183	Disconnected	<15.5 ppb	N/A		
Bubbler F20	23.7	Disconnected	<15.5 ppb	N/A		
Water Fountain FT5	20.3	Disconnected	<15.5 ppb	N/A		
Water Fountain FT7	376	Disconnected	<15.5 ppb	N/A		
Wedgwood Elementary Sc	hool					
Water Fountain FT5	280	Disconnected	<15.5 ppb	N/A		
			11			
Whitman Elementary School						
Fountain	17.7	Disconnected	<15.5 ppb	N/A		
			11			
Orchard Valley Middle School						
Steamer 2	400	Not in use for > 5 yrs	s. <15.5 ppb	N/A		
		- 5	11			

Τ	• • •	- 1
In	nu	aı

	Initial Test	Remediation	<u>Flush Test</u> Re	emediation			
Bunker Hill Middle School							
Steamer 1	70	Not in use for $>$:	5 yrs. <15.5 ppb	N/A			
Steamer 2	34.1	Not in use for $>$:	• • • •	N/A			
Sink S10	50.2	Disconnected	<15.5 ppb	N/A			
Sink S14	21	Disconnected	<15.5 ppb	N/A			
Sink S15	19.8	Disconnected	<15.5 ppb	N/A			
<u>Chestnut Ridge Middle Scl</u>	nool						
Steamer 1	70	Not in use for > 5		N/A			
Steamer 2	34.1	Not in use for > 5		N/A			
Sink S20	125	Disconnected	<15.5 ppb	N/A			
Sink S14	21	Disconnected	<15.5 ppb	N/A			
Sink S15	19.8	Disconnected	<15.5 ppb	N/A			
High School O'Brien Hall							
Hose Bib HB2	258	Disconnected	<15.5 ppb	N/A			
Hose Bib HB3	91.4	Disconnected	<15.5 ppb	N/A			
<u>High School – Core</u>							
Fountain FT3A	267	Disconnected	<15.5 ppb	N/A			
Fountain FT3b	582	Disconnected	<15.5 ppb	N/A			
High School 9-10 Wing							
Lab Sink LS14	330	Disconnected	<15.5 ppb	N/A			
Lab Sink LS15	9603	Disconnected	41	Labeled as			
				nondrinking water			
Lab Sink LS54	23.9	Disconnected	<15.5 ppb	N/A			
Lab Sink LS98	272	Disconnected	<15.5 ppb	N/A			
Lab Sink LS99	3455	Disconnected	<15.5 ppb	N/A			
Lab Sink LS43	71.5	Disconnected	<15.5 ppb	N/A			
Lao Shik LSTS	/1.5	Disconnected	<13.5 pp0	1 V/ <i>I</i> 1			

High School 11-12 Wing

Sink S22	362	Disconnected	<15.5 ppb	N/A
Fountain FT15	40	Disconnected	<15.5 ppb	N/A
Fountain FT25	31.4	Disconnected	<15.5 ppb	N/A
Fountain FT30	27.5	Disconnected	<15.5 ppb	N/A
Lab Sink LS17	5225	Disconnected	18.3	Labeled as nondrinking water
Lab Sink LS59	140	Disconnected	<15.5 ppb	N/A
Lab Sink LS7	256	Disconnected	<15.5 ppb	N/A
Lab Sink LS79	386	Disconnected	<15.5 ppb	N/A
Lab Sink LS80	64.7	Disconnected	<15.5 ppb	N/A
Lab Sink LS81	25.3	Disconnected	<15.5 ppb	N/A

These lab tests are posted on the website for your review.

Very truly yours,

9. Bour ngu

Joseph N. Bollendorf Superintendent of Schools

cc. Board of Education